

ALFA ROMEO ALFETTA, 1975-80; GTV6, 1981-86

STEEL BODY PANELS

		Item No.	Item No.	Price
A	Driver	Pass.		
B	Front fender steel rear repair section	93414	93413	\$ 97.50
A	Front fender liner, steel front section	03682	03683	89.50
C	Front fender liner, steel rear section	03599	03598	79.50
D	Front inner fender steel repair panel	93408	93409	174.95
E	Front inner fender steel reinforcement	93411	93412	114.25
F	Rear fender front steel repair section	93416	93415	64.50
G	Rear wheel arch repair panel	93312	93313	75.50
H	Grille, GTV6 (not incl. center badge)	03755	—	379.00

RUBBER MOLDING


-	Rubber door gasket	43687	43687	\$ 77.95
-	Rubber windshield molding	43645	—	279.50
-	Rubber rear hatch molding	82743	—	68.50
-	Sunroof molding (sides & front only)	43526	—	84.50

MISCELLANEOUS

-	Power window motor (only)	22004	22004	\$160.95
-	Rear hatch strut	30801	—	89.50
-	Floor pan plug, 2½" rubber	43685	—	3.95
J	Brake or clutch pedal rubber pad	27004	—	7.50
K	Hood prop slide (GTV6 only)	03611	—	34.65
-	Rocker panel clips (GTV6 only)	25099	25099	7.45
L	Sunvisor catch (GTV6 only) New!	30359	30359	12.65




ALFA ROMEO MILANO, 1987-89



	Item No.	Item No.	Price	
A	Driver	Pass.		
A	Rear wheel arch repair panel	93395	\$39.50	
B	Inner door handle, front or rear	13315	13314	26.25
-	Sunroof molding (felt-covered)	43526	—	84.50

ALFA ROMEO 164, 1991-95



	Item No.	Item No.	Price	
A	Driver	Pass.		
A	Fog lamp assembly, 1991-93*	23373	23376	\$149.50
A	Wiring connector for #23373/23376	23379	23379	25.75
B	Front side marker light assembly*	—	23364	95.25
C	Rear side marker light assembly*	23365	23366	89.50
D	Front outer door handle (unfinished)	13318	13319	47.95
E	Rear outer door handle (unfinished)	13321	—	42.50
E	Rear outer door handle (unfinished)	—	13322	33.55
-	Fuel filler door (lid)	—	03563	128.50
F	Tail lamp assembly	23369	23371	149.50
G	Power window regulator w/motor, front	40515	40529	168.50
-	Power window regulator w/motor, rear	40531	—	109.50
-	Sunroof molding, felt-covered rubber	43526	—	84.50
-	Hood lid strut	30828	30828	59.50
-	Trunk lid strut	30817	30817	34.25
H	Brake or clutch pedal pad (5-spd. only)	93565	—	2.95

* These also fit 1994-95 except LS

CUSTOMER PROFILE: BENITO MORENO



This 1966 Fiat 1500 Cabriolet is far from finished, but it's already come a long way. When Benny Moreno bought this car from a friend in July of '08, it was basically a collection of pieces.

"When I got it, it was just a great big pile of what my son called 'junk,'" he explained. "It didn't have a top or a windshield, the trunk deck was off it and one of the wheels was lost. It was in a shambles. I think they were in shock when they helped me unload it here!"

Immediately Moreno and his son Tony got to work. By February, it was in our parking lot and being gawked over by our staff!

POWER WINDOW REGULATORS

FOR ALFA ROMEO SPIDERS



Power window motor only, 1978-94, Fits either side, #22004, \$160.95 ea.

Retrofit power window regulator kit, 1978-94,

Driver Side, #40537, \$219.00

Passenger Side, #40538, \$219.00